

**Bid Round 59**  
**Questions & Answers**

Carlson TV & Electronics  
Commerce # 54880-2647-23-A  
DNR BRRTS # 03-16-533230

Question: Has the depth to bedrock/depth to groundwater been established at this site? If so, could you please provide this information?

Answer: As stated in the site investigation document available at the Copy Shop, bedrock was not encountered during site investigation soil borings which reached a maximum depth of 36 feet below ground surface (BGS). Groundwater was encountered in sand stringers at depths ranging from 27-33 feet BGS.

Question: Do any other wells currently exist on site?

Answer: As stated in the site investigation document available at the Copy Shop, there are currently five monitoring wells (MW-1, MW-2, MW-3, MW-4 and MW-5) present on the site. Wells MW-1, MW-3, MW-4 and MW-5 are also referenced in Section 2 of the bid document under the Minimum Remedial Requirements subsection.

Question: The bid requests quarterly groundwater monitoring of the site's monitoring well network. Should bidders assume that this network only includes the wells being installed under this scope of work?

Answer: No, see above.